

Name: \_\_\_\_\_

# CDL Inspection Section 4 & 5

- |   |                             |
|---|-----------------------------|
| 1. Valve stem is straight_____ _ _____. C   | A. fittings leaks           |
| 2. Tire_____has been checked with a _____and is at manufacturer's specification. M      | B. Broken                   |
| 3. Top of tire is_____evenly with at least 4/32 inch tread remaining. P                 | C. with a cap               |
| 4. Grab the Mirror - It's firmly_____, not broken & clean. O                            | D. Breakers                 |
| 5. Open the Door - It_____&_____properly,_____ are tight,_____is not torn. U            | E. triangles                |
| 6. _____roll up and down L  | F. closed                   |
| 7. There are no_____under the pedals. H   | G. vented tight             |
| 8. There is a 10 BC fire extinguisher properly charged &_____. S                        | H. obstructions             |
| 9. Battery box &_____are properly attached to the_____. J                               | I. Tight                    |
| 10. Battery Box 4 12v N   | J. cover frame              |
| 11. Battery Box Cell Caps I   | K. straps gasket            |
| 12. Steps Mounted R   | L. Windows                  |
| 13. Steps Not T   | M. pressure gauge           |
| 14. Steps Not B   | N. batteries                |
| 15. Tank is mounted to the frame with_____, there's a_____between the strap and tank. K | O. attached                 |
| 16. Fuel lines &_____have no cuts, cracks, frays or_____. No leaks under the tank. A    | P. wearing                  |
| 17. There is a_____fuel cap with gasket & it is_____. G                                 | Q. holes tears              |
| 18. Sleeper has no_____or_____in the skin. Q  | R. Securely                 |
| 19. Inside this door 3 warning E  | S. mounted                  |
| 20. Inside this door Spare Fuses or D   | T. Cracked                  |
| 21. This inside Door is F   | U. opens closes hinges seal |